INVOICE # 10-35019

May 12, 2021 09:58 AM

SALES PERSON

PRODUCT

DESCRIPTION

Chris Slyman chris.slyman@slymanbros.com



τοται

14755 Manchester Rd, Ballwin, MO 63011 Slyman Bros (West County) Phone: 636-227-7727

BILLING INFORMATION	DELIVER TO
Ann Yost	Ann Yost
l-y@sbcglobal.net	l-y@sbcglobal.net
15222 Brightfield Manor Dr	15222 Brightfield Manor Dr
Chesterfield, Missouri, 63017	Chesterfield, Missouri, 63017
636-530-1656	636-530-1656

PRICE

moboer	DESCRIPTION	THEE	211	TOTAL
WRQA59CNKZ SN: TMX5048702	36-INCH WIDE COUNTER DEPTH 4 DOOR REFRIGERATOR - 19.4 CU. FT. Install : Freestanding Fridge Standard Install (to existing copper or stainless waterline) Warranty : 5 Year Extended Warranty Delivered On: 2021-05-20 Quantity: 1	\$1,799.95	1	\$1,799.95

Haul Away Old: Yes (1)

OTY

OTES	Subtotals	\$1,799.95
	Sales Tax (West County)	\$157.28
	Extend Warranty Charge	\$249.95
	Install Charge	\$25.00
CHRIS SLYMAN - 09:56 AM 05-12-2021	Delivery Charge	\$0.00
	Total	\$2,232.18
Fridge is coming from Ballwin store. Install to existing waterline, haul away old. BE VERY CAREFUL, customer has saddle valve and it is located in basement.	Record Payment Amount Paid	
	Payment: check	\$2,232.18
	Transaction Number: 5821	
	Date: 05/12/2021	

Balance Due (USD)

\$0.00

DISCLAIMER

Delivery date is subject to change if the item goes on manufacturer backorder. Backorders may occur and availability dates rely solely on the manufacturers, not Slyman Bros. Special order items, out-of-box inventory, closeouts, and discontinued items are non-returnable and non-cancelable and must be serviced if issues occur. Slyman Bros charges for standard install prices only; any additional charges past a standard install must be paid directly to the contractor at the time of installation. Once items are delivered: Cosmetic damage and property damage MUST be reported at the time of delivery; by signing the delivery document you are agreeing to this and forfeiting your right to claim damage. All promotional rebates must be claimed by the consumer and the consumer has full responsibility.